

HISTORIC AMERICAN ENGINEERING RECORD

Index to Photographs

HAER,
GA,
26-SAV,
55J-

HAER No. GA-1-J

Central of Georgia Railway, Savannah Repair Shops & Terminal Facilities,
Carpentry Shop
Site bounded by West Broad, Jones,
West Boundary and Hull Streets
Savannah
Chatham County
Georgia

Note: These photographs are U.S. Government materials and not subject to copyright, however, the courtesy of a credit line identifying the Historic American Engineering Record and the photographer, Jack Boucher, would be appreciated. All photographs were taken by Jack Boucher in August 1976.

- GA-1-J-1 N elevation of Carpentry Shop.
- GA-1-J-2 W elevation of Carpentry Shop.
- GA-1-J-3 Former S elevation of Carpentry Shop that was enclosed by Pattern Room in c. 1855.
- GA-1-J-4 View looking S down length of Carpentry Shop showing roof trusses.
- GA-1-J-5 Detail of roof trusses.
- GA-1-J-6 Three-quarter view of roof truss.
- GA-1-J-7 Truss and wall connection.
- GA-1-J-8 Detail of pulley assembly bolted to bottom chord of truss.
- GA-1-J-9 View of NW corner showing truss framing at hip gable.
- GA-1-J-10 View looking W in basement area under Pattern Room showing pressure tank and belt-pulley assembly mounted on floor.
- GA-1-J-11 View looking N in basement area under Carpentry Shop showing piers and foundation walls.

* See HAER No. GA-1 for written historical and descriptive data and reduced copies of measured drawings.